

A
 $S=1,6\text{mA/V}$
 $\mu=68$
 $R_i=40\text{k}$
 $P_a=\text{max. } 1\text{W}$

B
 $S=6,5\text{mA/V}$
 $\mu=6$
 $R_i=925\ \Omega$
 $P_a=\text{max. } 7\text{W}$

