

$S_p = 7,5 \text{ mA/V}$   
 $R_i = 200 \text{ k}$   
 $P_a = \text{max. } 2,5 \text{ W}$

$S_T = 8,5 \text{ mA/V}$   
 $R_i = 5,4 \text{ k}$   
 $\mu = 46$   
 $P_a = \text{max. } 2,5 \text{ W}$

