

pentode:
 $S = 5.2 \text{ mA/V}$
 $R_i = 400 \text{ k}$
 $P_a = \text{max. } 2.8 \text{ W}$

triode:
 $S = 8.5 \text{ mA/V}$
 $R_i = 5 \text{ k}$
 $\mu = 40$
 $P_a = \text{max. } 2.7 \text{ W}$

