


$S_c = 400 \mu A/V$
 $V_{g1} = -3 \dots -25V$
 $R_i = 2M$



$S = 1.4 mA/V$
 $V_{g1} = -3 \dots -25V$
 $R_i = 1M$

